



## STAR ONLINE PUBLICATION




**Case Number:** S2223000060

**Release Date:** August 2022

**Symptom/Vehicle Issue:** Hood Is Under Flush To The Fender

**Customer Complaint/Technician Observation:** Customer or technician may notice the hood on a vehicle appears under flush. Customer may request adjustment.



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.**



## STAR ONLINE PUBLICATION



**Discussion:** For awareness, the specifications for hood to fender flush are as follows:

Nominal: Hood U/F 2.0 +/- 1.5  
Transition to 2.2 at front +/- 1.5  
Transition to 0.0 at rear +/- 1.5  
Consistent within 1.5 (frt to back)  
Side to side within 1.9

If the vehicle meets these specifications do not adjust the hood or body panels. For additional information on gap and flush refer to Service Library 23 - Body / Body Structure / Gap and Flush / Specifications GAP AND FLUSH DIMENSIONS

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.**