



NUMBER: 23-033-22

GROUP: 23 - Body

DATE: August 5, 2022

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 22-145, date of issue August 05, 2022. All applicable Sold and Un-Sold RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty. This RSU will expire 18 months after the date of issue.

SUBJECT:

Windshield Washer Nozzle Spray Not Uniform

OVERVIEW:

This bulletin involves inspecting and if necessary, replacing one or both windshield nozzles.

MODELS:

2022 (LA) Dodge Challenger

NOTE: This bulletin applies to vehicles within the following markets/countries: North America.

NOTE: This bulletin applies to vehicles built on or after March 08, 2022 (MDH 0308XX) and on or before April 18, 2022 (MDH 0418XX) with a Shaker Package (Sales Code AZS).

SYMPTOM/CONDITION:

The customer may describe the following:

- Windshield washer nozzles do not have sufficient coverage between two nozzles.

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RSU VIN list, perform the Inspection Procedure.

This RSU only applies to vehicles on the RSU VIN list.

1. Operate and inspect the windshield washer nozzle fluid spray from both nozzles.

2. Was an uneven spray pattern noticed from one or both washer nozzles (Fig. 1) ?
- YES>>> Proceed to [Step 1](#) of the Repair Procedure.
 - NO>>> This bulletin has been completed, use inspect LOP (23-43-20-97) to close the active RSU.



Fig. 1
Uneven Washer Nozzle Pattern on Driver Side

PARTS REQUIRED:

Qty.	Part No.	Description
1 or 2 (AR)	68260442AB	Nozzle, Windshield Washer

REPAIR PROCEDURE:

1. Replace one or both windshield washer nozzles. Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info>08 - Electrical / 8R - Wipers/Washers / Nozzle, Washer / Removal / Installation.
2. Operate the washer system and verify spray pattern coverage.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
23-43-20-97	Nozzle, Windshield Washer - Inspect (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
23-43-20-98	Nozzle, Windshield Washer - Inspect and Replace One or Both (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------

