

23-005: Model 365, 367, and 389 Clutch Pedal Linkage Lube Service Interval

10/6/2022

 [Edit](#)  [Clone](#)

23-005

Section

Clutch - 23

Subject

23-005: Model 365, 367, and 389 Clutch Pedal Linkage Lube Service Interval

Whats New Abstract

Clutch pedal linkage lubrication service interval information is missing from the Service manual for Model 365, 367, and 389 chassis.

Condition

Service interval information for the clutch pedal linkage lubrication is missing from the Service manual for Model 365, 367, and 389 chassis.

Chassis Affected

Model 365, 367, ad 389 chassis.

Action

Information Only

Clutch pedal linkage lubrication should be included with chassis lubrication intervals, every 15K miles, or 24K km, for Off-Highway/Vocational/City Delivery and 30K miles, or 48K km, for On Highway/Line Haul.

Parts

Parts are available from PACCAR Parts.

Quantity	Part Number	Description
1	Source Locally	Lithium Complex NLGI GC-LB

Procedure

No Procedural Documents