

Subject: Engineering Information - Intermittent No Start But Vehicle Has Power

This PI has been revised to end the need for information from the field. Please discard PIE0703A.

| Brand: | Model: | Model Year: | | VIN: | | Engine: | Transmission: |
|-----------|---------|-------------|------|------|----|--|---------------|
| | | from | to | from | to | | |
| Chevrolet | Equinox | 2021 | 2022 | — | — | Equipped with 1.5L Engine (RPO LYX) | — |
| GMC | Terrain | | | | | | |

If you encounter a vehicle with the above condition, refer to *Starter Malfunction* in SI for further diagnosis.

| | |
|-----------------|--|
| Version | 3 |
| Modified | Released June 02, 2022 Revised June 13, 2022 – Revised to remove 2019-2020 Model Year. Revised October 14, 2022 - Ended the need for further information from the field. |