

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.

Document Information

Location: Interior

Topic: The luggage bin or tailgate switch has collapsed inside the facia

Condition: Permanent

Diagnostic Trouble Codes: N/A

Measure

If you receive a customer complaint regarding the luggage bin or tailgate facia switches having pushed through inside the facia, please follow SIS instruction: '**Interior / Interior Systems / Facia / FA-RM-10N001-01-013 - Remove/Install updated bracket - Luggage bin/tailgate open switches**' to install an updated facia/button bracket.

The new bracket part number required for this repair are stated in the 'Parts Information' section below. Depending on RH or LH drive vehicle, please order the correct bracket kit RH or LH.

The facia is no longer required to be replaced to rectify this complaint.

Parts Information

22NB880GP - FACIA SWITCH BRACKET KIT-**LHD-LH**

22NB881GP - FACIA SWITCH BRACKET KIT-**RHD-RH**

Attachments

N/A

KA Update Information

05/10/2022 - First release

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.