

Urgent - Immediate Action Required

McLaren Artura Body Harness Rework

SENSITIVITY: Restricted

Bulletin type:	Service Campaign
Reference number:	N/A
Campaign reference:	SCB 16 M 001
Attention:	Retailer Aftersales Managers, Retailer Service Managers, Retailer Service Advisors, Retailer Technicians
Affected vehicles:	McLaren Artura
Situation:	Addition of spacer bushes and felt tape to the body harness and carbon tub
Procedure:	Action affected vehicles prior to handover. Please refer to the information outlined in this document to complete the required work
Date:	07 October 2022

Immediate action is required to rework vehicles prior to handover

For more details, please read the bulletin below.

This bulletin will cover:

1. Overview
2. Procedure
3. Parts Information
4. Warranty Information
5. Affected Vehicles

1. Overview

Through continuous product quality monitoring, McLaren Automotive has identified that on certain McLaren Artura vehicles that a body harness enhancement is required in the area behind the HVAC shroud of the tunnel console.




Figure 1: Location of rework area

2. Procedure

To carry out the required rework, two split spacer bushes are required to be fitted around a specific cable of the body harness and a felt tape applied to the carbon tub. Document SCB 16 M 001 WI (attached with this bulletin), contains the relevant work instructions and care points to ensure the work is carried out to bring the vehicle up to the current manufacturing standard.

In cases where any damage to the body harness insulation sleeve is present, please submit a Technical Request including pictures to the Technical Support team for further advice.

3. Parts Information

The below parts are required to action this rework and can be ordered in the usual way via Unidial 2.

PART NUMBER	PART DESCRIPTION	QUANTITY
00RA357	Protector - Pipe	2
16AF810CP	Felt tape	1

4. Warranty Information

Submit a claim to the McLaren Warranty department following completion of the work, using the following details.

DESCRIPTION	REPAIR TIME
McLaren Artura Body Harness Rework – LHD vehicles 1 speaker	1.70 hrs
McLaren Artura Body Harness Rework – LHD vehicles 2 speakers	1.90 hrs
McLaren Artura Body Harness Rework – RHD vehicles 1 speaker	1.70 hrs
McLaren Artura Body Harness Rework – RHD vehicles 2 speakers	1.95 hrs

5. Affected Vehicles

Affected vehicles will be flagged in the Retailer Portal when next opening a Workshop Visit related to the vehicle.

Vehicles will require this rework before handover.

Your Regional Aftersales Manager will contact you with a list of affected vehicles.

If you have any questions, please speak to your Regional Aftersales Manager.

The information contained in McLaren bulletins is for internal use only by McLaren Authorised Retailers and must not be published on external websites or social media forums etc.

The McLaren data classification policy applies to all full time, part-time and fixed term employees of McLaren and all workers including, contractors, consultants, suppliers, and third parties who have access to McLaren data and/or systems. This policy includes all information held by, or on behalf of, McLaren in any form and all information systems/services used by, or used to store data belonging to, McLaren.

Part numbers listed in McLaren bulletins are for reference only. Always check with the parts department to verify the latest part numbers.

Prices are correct at the time of publication and are subject to change. It is recommended that you review the latest pricing on Unidial 2.

All bulletins (Information/Campaign/Recall) issued by McLaren Automotive Limited ("McLaren") are intended only for use by technicians who have attended McLaren technical training courses. McLaren trained technicians have the equipment, tools, safety instructions and the know how to perform the job properly and safely. McLaren bulletins are written to inform McLaren technicians of conditions that may occur on some McLaren vehicles, or to provide information that could assist diagnosing a McLaren vehicle. Part numbers listed in McLaren bulletins are for reference only. Always check with the parts department to verify the latest part numbers.