

N733 UPS5621 – ACTIVE ROLL CONTROL MODULE (ARCM)



UPDATE PRIOR TO SALE N733 - ACTIVE ROLL CONTROL MODULE (ARCM) INITIALIZATION FAILURE

AFFECTED MODELS	22-23MY New Range Rover
VOLUME AFFECTED	USA 1,085 Canada 113
REPAIR	The front and rear ARCMs, in a small percentage of cases, are susceptible to intermittent initialization failure when the vehicle is started, and an amber suspension fault warning lamp may be illuminated of the Instrument Cluster Panel. Retailers are to update to both the front and rear ARCM ECU before vehicle sale.
REPAIR TIME	0.4 hrs + DIDO
CAMPAIGN LAUNCH	September 21st, 2022
Notes	There are 60 affected vehicles remaining in Retailer stock which need this repair completed prior to sale and delivery. Check BBSS inventory reports or the Warranty Portal Campaign reports for affected VIN at your store.