

Near Field Sensing Feature Degradation

20-23MY DEFENDER, 21-23MY DISCOVERY, DISCOVERY SPORT,
RR EVOQUE, VELAR, F-PACE, E-PACE, XF, I-PACECustomer Voice:

- Surround camera, 360 Park aid features are not operating

Technical Description:

- Near Field Sensing Module (NFSM) DTC's are not logged in confirmed/active status
- DTC B115E-31 is confirmed in the Infotainment Compute Control Module (ICCM)
- Cause is due to a loss in communication from the CAN bus

Status:

- **Do NOT replace the Near Field Sensing Module for this issue.**
- Follow the procedures outlined in SSM75618
- Submit a TA only if the issue persists after following the procedure listed in SSM75618

