

## BODY & CHASSIS

Deployable Side Steps – Noisy When Operating	22– 23MY New Range Rover (L460)
<p><b>Customer Voice:</b></p> <ul style="list-style-type: none"><li>– A customer may complain of a creak or ticking type noise from the deployable side steps when they are operating to deploy or stow.</li></ul> <p><b>Technical Description:</b></p> <ul style="list-style-type: none"><li>– Noise concerns from the deployable side steps linkage is under investigation.</li></ul> <p><b>Status:</b></p> <ul style="list-style-type: none"><li>– Engineering is currently investigating this concern.</li><li>– SSM 75830 has been published to provide diagnostic guidance for this concern.</li><li>– Additionally, the SSM requests an EPQR be submitted with details from where the noise is heard and if possible, please provided a brief video of the concern to aid in the ongoing investigation.</li></ul>	