

N733 SERVICE ACTION – ACTIVE ROLL CONTROL MODULE (ARCM) INITIALIZATION FAILURE



UPDATE PRIOR TO SALE N733 – ACTIVE ROLL CONTROL MODULE (ARCM) INITIALIZATION FAILURE

AFFECTED MODELS	22-23MY New Range Rover 23MY New Range Rover Sport
VOLUME AFFECTED	USA 1,085 Canada 113
REPAIR	The front and rear ARCMs, in a small percentage of cases, are susceptible to intermittent initialization failure when the vehicle is started, and an amber suspension fault warning lamp may be illuminated of the Instrument Cluster Panel. Retailers are to update to both the front and rear ARCM ECU before vehicle sale.
REPAIR TIME	0.4 hrs + DIDO
CAMPAIGN LAUNCH	September 12th, 2022
Notes	There are c. 76 affected vehicles in Retailer stock which should have this repair completed prior to sale and delivery.