

## STAR ONLINE PUBLICATION















Case Number: S2218000019

Release Date: September 2022

**Symptom/Vehicle Issue**: Customer's complaint includes Mil-on/check engine lampon.

**Customer Complaint/Technician Observation:** Upon further inspection, a fault for P0300-Multiple Cylinder Misfire may be set in the PCM.

**Discussion**: Perform published diagnostic routine for P0300 found in Service Library. If diagnostics direct to a condition of trouble-not-found, engineering is investigating this issue at this time. No repairs are recommended.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found

Stellantis US LLC Version 4.5 06/08/2022