



STAR ONLINE PUBLICATION



Case Number: S1902000008 REV. A

Release Date: September 2022

Symptom/Vehicle Issue: Air Suspension Compressor Module Assembly Replacement.

Discussion:



When servicing an Air Suspension Control Module assembly do not remove this fastener (circled in **RED** above). If the plastic fitting is removed from the compressor assembly an internal leak may occur resulting in nitrogen loss.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.




STAR ONLINE PUBLICATION



Push in the brown retainer ring (3) on the air compressor and disconnect the outlet hose (2).

Push in the brown retainer ring (4) on the air compressor and disconnect the inlet hose (1).



Proper removal of the intake and outlet line assemblies

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.