

STAR ONLINE PUBLICATION















Case Number: S2208000165

Release Date: September 2022

Symptom/Vehicle Issue: No Start, No Crank, Interior Lamps Flicker, Interior Camera

Inoperative

Owner Complaint/Technician Observation: Owner complains that the vehicles interior lamps flicker, the vehicle may not start at times or the interior camera if equipped has no display. Technician observed the vehicle was not setting any Diagnostic Trouble Codes (DTC's), and the Radio Frequency Hub (RFHUB) goes offline intermittently.

Repair Procedure: Inspect ground location G951A, clean and secure the ground as needed. No parts required Fig 1 and 2.




Fig 1

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.

Stellantis US LLC Version 4.5 07/22/2022



STAR ONLINE PUBLICATION


















Fig 2

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.

Stellantis US LLC Version 4.5 07/22/2022