

WLL0 Workshop campaign - Re-programming DME control unit

WLL0 Workshop campaign - Re-programming DME control unit

ID Number	WLL0
Models	Macan (95B)
Model Years	2019-2020
VIN list	Attached
Number of Affected VINs	20,028
Issue Description	New DME control unit software is available for the Macan that optimizes exhaust gas post-treatment. As a result, the DME control unit must be re-programmed on the affected vehicles.
What Dealers should do	Please arrange for this measure to be carried out as soon as possible on affected vehicles. As of the time of this posting, the repair is immediately available.
California Dealers only	The Department of Motor Vehicles (DMV) in California may require that the customer furnish proof of completion of this Workshop Campaign in the form of a copy of the dealer's repair order, including a signed "Proof of Correction" certificate, before the next renewal of the vehicle registration. You must supply this documentation to the customer only after the campaign has been completed. Please instruct the customer to retain the signed "Proof of Correction Certificate" within their vehicle records.
Customer Notification	Will be posted at a later date
TI Number	No. 175-20