

Technical Journal

TITLE:

Footwell lights, not working after software update 2.2

REF NO: TJ 36345.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7515		ISSUE DATE: 2022-09-08	STATUS DATE: 2022-09-14
FUNC GROUP: 3540	FUNC DESC: Lighting, interior	Page 1 of 1	

DESCRIPTION:

If customer complains about footwell lightning not working after software update 2.2 (release 2022w26), do not start fault tracing. Read more under Service.

CSC Customer Symptom Codes

Code	Description
YE	Courtesy lighting/Does not work

DTC Diagnostic Trouble Codes**Vehicle Type**

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
534							2021-9999		-	202007-999952

SERVICE:

For cars with VDN code PD01, the footwell lights will not work after software update 2.2. This will be corrected in a later software update. Timing not decided yet.

Warranty claims will not be accepted for this TJ.

LABOR TIME:

Labor time subject to change without notice.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report Polestar" and sub concern area "Support not needed Polestar", use function group 3540.