



Preliminary Information

PIT5917B No Selection In The DIC To Reset The Fuel Filter Life (Canada and Mexico Vehicles Only)

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Suburban	2021 - 2022	All	All	3.0L LM2	All
Chevrolet	Tahoe	2021 - 2022	All	All	3.0L LM2	All
GMC	Yukon Models	2021 - 2022	All	All	3.0L LM2	All

Involved Region or Country	Canada and Mexico Vehicles Only
Additional Options (RPO)	With RPO UHS and LM2
Condition	Some customers may comment that they are unable to reset the fuel filter monitor system. When scrolling through the DIC there is no selection for fuel filter life.
Cause	IPC Calibration

Correction:

Engineering has released updated IPC calibrations to correct this issue. Reprogram the IPC with the latest calibration currently available in SPS following SI instruction "P16 Instrument Panel Cluster Control Module: Programming and Setup".

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2810195	Instrument Cluster Reprogramming with SPS	Used Published Labor Time

Version History

Version	3
Modified	05/11/2022 - Created on. 09/26/2022 - Updated to make a correction in the Correction Sections 10/10/2022 - Updated the Cause, Correction and Warranty sections.



GENERAL MOTORS

© 2022 General Motors. All Rights Reserved.