



Preliminary Information

PIT5702D Installation of Upfitter Auxiliary Switches (RPO 9L7)

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500 (New Model)	2019	All	All	All	All
Chevrolet	Silverado 1500	2020 - 2023	All	All	All	All
Chevrolet	Silverado 2500HD/3500HD	2020 - 2023	All	All	All	All
GMC	Sierra 1500 (New Model)	2019	All	All	All	All
GMC	Sierra 1500	2020 - 2023	All	All	All	All
GMC	Sierra 2500HD/3500HD	2020 - 2023	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	9L7
Condition	A Dealer or Upfitter may be looking for information on installing RPO 9L7 Upfitter Auxiliary Switches. The Upfitter Auxiliary Switches are located under the climate controls in the center of the dash.
Cause	Information not readily available in Service Information (SI.)

Correction:

Reference the latest version of GM Upfitter Integration Bulletin 153. The information can be found at <http://www.gmupfitter.com/> under the "Technical Bulletin" Tab and then "Show all bulletins."

NOTE: Installation of the Upfitter (AUX) Switches and supporting components are NOT a GM Warranty or PDI covered labor cost. The installation of the switches/components are intended to be performed by the upfitter as a part of the overall vehicle upfit and the labor cost associated with that installation be covered in the upfitter's estimate to its customer. Installation, when performed by a GM dealer, the labor charges associated with that install are the responsibility of the customer/vehicle purchaser.

Version History

Version	5
Modified	08/07/2019 - Created on 10/17/2019 - Updated to add statement that this installation is considered a customer pay installation, not Warranty or PDI expense. 01/06/2021 - Updated to add 2021 Model Year 01/06/2022 - Updated to add 2022 Model Year 10/13/2022- Updated to add the 2023 Model Year



GENERAL MOTORS

© 2022 General Motors. All Rights Reserved.