

Motorcycle Service Group
Overseas Service Department
8686, Miyakoda, Kita, Hamamatsu, Shizuoka, Japan 431-2102
Tel: 81-53-528-8118, Fax: 81-53-528-8141

Page	1 of 2
Date	Oct. 31, 2022
Our ref.	J7-221031

TO: Suzuki Motorcycle Distributors
ATTN.: Managing Director
Service Manager

SUBJECT: GSX-R1000AM3 Front Wheel Speed Sensor Inspection in Distributor Warehouse

Dear Sirs and Madams,

This letter is to request you to inspect “Front Wheel Speed Sensor” of GSX-R1000AM3 stock units in your distributor warehouse.

We were informed from our production plant that they have found two units were released with Front Wheel Speed Sensor for other model.

Therefore, Suzuki Motor Corporation (SMC) is requesting you to inspect Front Wheel Speed Sensor of GSX-R1000AM3.

You are kindly requested to stop wholesale this affected unit to your dealers until the inspection work is done.

We apologize for any inconvenience this may cause to you. Your kind understanding and cooperation will be highly appreciated.

Very truly yours,



Shinji Ishikawa
Department General Manager
Overseas Service Department
Suzuki Motor Corporation

1. Proposed schedule

We would like to request you of the schedule as follows.

- (1) Check stock status at your warehouse
- (2) Stop delivery to dealers
- (3) Confirm inspection work procedure
- (4) Decide inspection work date
- (5) Perform inspection work
- (6) Report the inspection result to SMC

2. Affected Model

Model: GSX-R1000AM3

Affected VINs and quantity: Please refer to the VIN list (ANNEX2).

Please fill "Inspection result" and "Completion date" in ANNEX2, and send it back to us after you complete the work.

3. Warranty Reimbursement Information

The labor cost and any other costs (example. space fee, labor cost for forklift, temporary workers, etc.) will be reimbursed upon your statement. Please submit actual cost to SMC.

The following information is a reference to Labor hours for inspection work.

Claim category	2 (Campaign)
Trouble Code	97-J7
Basic code	MD9999

Inspection Result	Model	Causal Part Name	Causal Part No.	Q'ty	Flat Rate(Hr)
OK (Inspection only)	GSX-R1000AM3	SENSOR COMP, FR WHEEL SPEED	55710-17K00	0	0.2
NG (With Replacement)	Wait further information from SMC				

Note: NG units are maximum two units. If you face two NG units before inspecting all units, no need inspect the other units.

4. Repair Instruction

The repair instruction of ANNEX1 is available on SCAN FD.

Please download the files from below.

SCAN-FD - Download - Service - Document Files for Motorcycle

ANNEX1_GSX-R1000A_Repair_Instruction_of_FR_Wheel_Speed_Sensor_Inspection

5. Attachment

ANNEX1_GSX-R1000A_Repair_Instruction_of_FR_Wheel_Speed_Sensor_Inspection

ANNEX2: (Country name) _VIN_List.xlsx

END