

TECHNICAL NEWS 227



Notice Information

Ref	22621
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Parts / Accessories Coordinator, Sales Executive, Clothing Sales, Sales Manager, Aftersales Manager, Service Leader / Advisor, Accounts / Admin, Marketing Executive
Subject:	Service/Technical

TOL NOTICE (US&CA) – October 27, 2022

TOL Ref. #22621-SVC

TECHNICAL NEWS 227

Technical News 227 is now available for download on the Triumph Technical News library located at **Triumph Online > Service/Technical > Technical News** or you can consult the attached **Technical News 227** PDF. Please ensure your workshops and all relevant staff are aware of the contents and any absent staff are informed upon their return. Please also update your workshop service manuals, procedures and have a printed copy available where appropriate.

PLEASE ENSURE ABSENT STAFF ARE INFORMED ON THEIR RETURN.

Contents		
Item	Subject	Model Affected
227.1	Ignition Switch	Tiger Sport 1050

Some affected motorcycles listed in the VIN range will have been modified and repaired by Triumph prior to their release from the factory. Unmodified motorcycles can be identified by checking the 'VIN Enquiry' on www.triumphonline.net. **Motorcycles in the affected VIN range must be modified prior to delivery to the customer, or at the next dealership visit.**

Consult **Triumph Online (TOL) / Service Bulletin Page** (Bulletin #227) or the attached **Service Bulletin #227** PDF for additional information including Fitting, Warranty Claim and Part Ordering instructions if applicable. Please also ensure that all relevant staff are up to date on these service instructions.

Reminder: Use the **"VIN Enquiry"** function within TOL (found under the **Service / Technical** drop-down menu) to search for any outstanding bulletins or recalls whenever a new motorcycle arrives, or a Triumph owner visits your dealership.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.