

QUARANTINE NOTICE

Reference number:	QN-31-1705	Issued: 08 November, 2022
Subject:	Check and if Necessary Install a Rear Licence Plate Plinth	
Model(s):	DBX, DBX707, DBX Straight-Six	
VIN Range:	Refer to the separately published list of affected Vehicle Identification Numbers (VINs)	
Applicable to:	United States, Canada, Mexico, Japan, China	
Distribute to:	After Sales Manager Executive Manager Service Manager Sales Manager	Warranty Staff Technician(s) Parts Staff

Reason for this Quarantine Notice

Aston Martin has found that the plinth for the rear licence plate may not be installed on some DBX vehicles. To correct this problem, check and if necessary install a rear licence plate plinth.

Workshop Procedure

1. Examine the rear licence plate to see if there is a rear licence plate plinth installed.
2. If the rear licence plate plinth is installed no further action is necessary and this workshop procedure is complete.
3. If the rear licence plate plinth is **not** installed, install the plinth for the rear licence plate (refer to Workshop Manual Procedure 31.03.BC).

Warranty Data**Procedure and Labour Time**

Description	Labour Time
Install a Plinth for the Rear Licence Plate	0.15

Part Data

Description	Part Number	Quantity
Plinth for the Rear Licence Plate (Canada & USA)	6G33-17B389-AE	1
Plinth for the Rear Licence Plate (Japan Mexico and Peru)	AD43-13418-BA	2
Blind Rivet (Japan Only)	702943	4
Plinth for the Rear Licence Plate (China)	CD33-17B389-DD	1