

VOLVO

TRUCKS DEALER BULLETIN

To: General Managers, Service Managers, Service Technicians, Warranty Managers
From: Volvo Trucks – Service
Date: November 30, 2022
Subject: Service Literature Published and Released in November, 2022
Bulletin: SLV22-011

The following summarizes the service literature that has been published and/or revised for the month.

SERVICE NEWS

BULLETIN #	TITLE	COMMENTS
	None Issued	

TOOL BULLETINS

BULLETIN #	TITLE	COMMENTS
STB22-004V	Front crankshaft spacer Installation tool	New

TECHNICAL SERVICE BULLETINS

BULLETIN #	TITLE	COMMENTS
	None Issued	

SERVICE PROGRAMS

BULLETIN #	TITLE	COMMENTS
	None Issued	

RECALLS

BULLETIN #	TITLE	COMMENTS
	None Issued	

V O L V O

TRUCKS DEALER BULLETIN

CASE BASED REASONING (CBR)

UPDATED SOLUTIONS

SOLUTION	TITLE	COMMENTS
CBR-328	Diagnostic Trouble Codes (DTC) P208064, P208464, P242B64 and P246F64 Lighting The Malfunction Indicator Lamp (MIL) - US17+OBD19 And Newer Emissions, Model Years 2020 and Newer	New diagnostic solution CBR-2196 has been created.
CBR-2132	Volvo Chassis - P05E662 Park brake Sensor/Switch Circuit Range/Performance, Signal Compare failure	Corrected DTC specified in title.
CBR-931	Automated Manual Transmission (AMT) Concentric Clutch Actuator (CCA), Diagnostic guidance for P107538	Added information for learning modules in Navigator.
CBR-2214	Turbo Compound 2nd Generation - EGR And/Or DPF Diagnostic Trouble Codes (DTC), Diagnostic And Repair Information	Updated EGR DP specification from 0.5 to 0.6.
CBR-607	Volvo Chassis - Equipped With An Automated Manual Transmission (AMT-C, AMT-D, I-Shift) - - Unable To Program Transmission Electronic Control Unit (TECU) That Comes With A Reman Transmission - US07 TO US14 OBD13	Corrected the title to reflect correct brand.
CBR-399	Vehicle Overspeed Warning Comes Active At A Lower Speed Than Expected; Vehicle Overspeed Warning In Driver Information Display (DID) - Model Year 2018 And Newer With New Style Instrument Cluster	Removed the following comment "If the vehicle overspeed alert is activating at too low of a speed on a VECU5 chassis contact Tech Support to have the parameter changes made." This issue has been resolved.
CBR-65	Timing Gear Plate With Integrated Gasket - Installation Instructions And Information	Updated note specifying when the timing gear cover and flywheel housing must also be replaced. Updated formatting for clarity. Updated tags and categories for improved searchability.