

- f. Allow update to complete. IM will reboot on its own during this process.
 - g. When complete, remove USB-C drive.
6. Verify updated software version: SETTING > SOFTWARE > SOFTWARE INFORMATION.
- a. **RA1250, RA1250S:** Software version (LM7) 5.1355.2_20221031 or later.
 - b. **RH1250S:** Software version (LM4) 5.1355.62_20221031 or later.

CREDIT PROCEDURE

NOTE

For vehicles within factory warranty only.

Credit Procedure:

Table 3.

ITEM	DATA
Claim Type	PRD/DEM/MC-PDI/Standard Claim
Problem Part Number	70900896 (RA1250/1250S)
	70900897 (RH1250S)
Quantity	Leave Blank
Primary Labor Code ⁽¹⁾	2830
Time	0.2 h
Customer Concern Code	9203
Condition Code	2830
<i>(1) Download may be required</i>	

NOTE

*Enter **M1569** in Events Comments.*