


BODY & CHASSIS

Second Row Seat Armrest Stowage Compartment Lid Will Not Latch	22– 23MY New Range Rover (L460), 23MY New Range Rover Sport (L461)
<p>Customer Voice:</p> <ul style="list-style-type: none">– A customer may report that the second row seat armrest storage compartment lid does not latch closed. <p>Technical Description:</p> <ul style="list-style-type: none">– The storage compartment lid may not latch due to a quality issue with the locking arm. <p>Status:</p> <ul style="list-style-type: none">– A revised locking arm has been developed to address this concern.– TSB JLRTB02106 has been published to provide a robust repair for this concern.– Please refer to this TSB should a customer express a concern.	 A photograph showing the interior of a vehicle, specifically the second row seat. The focus is on the center console armrest, which is upholstered in a dark grey or black leather-like material. The armrest is folded down, revealing a storage compartment. The lid of the storage compartment is visible, and it appears to be made of a dark, possibly plastic or coated metal, material. The surrounding area shows the seat's stitching and the interior trim.