


BODY & CHASSIS

Powered Loadspace Cover Does Not Open Correctly	23MY New Range Rover (L460),
<p>Customer Voice:</p> <ul style="list-style-type: none">- A customer may report that the powered loadspace cover does not open properly when actuated. <p>Technical Description:</p> <ul style="list-style-type: none">- The loadspace cover may not initiate the fold properly due to incorrect hinge break point angle. <p>Status:</p> <ul style="list-style-type: none">- SSM 75746 has been published to provide an interim solution to the concern.- The felt tape is from the Automotive Squeaks & Rattles Kit (JLR-NSL1001) available to order through Bosch.- Replacement Felts & Foam Packs (JLR-NSL1001/7) are also available to replenish the kit.	 <p>A 3D cutaway diagram of the loadspace cover mechanism. The diagram shows the cover in a partially open position, revealing the internal hinge assembly and the motor. The cover is brown, and the hinge components are blue and red. A green bar is visible on the top edge of the cover. The diagram is set against a light gray background.</p>