

Subject: Engineering Information – Front Upper Control Arm Ball Joint Separated from Socket

This PI has been revised to end the need for gathering information from the field. Please discard PIE0715A.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado	2019	2021	—	—	—	—
	Silverado 1500 LTD (RPO J21, VIN Digit 5 = W / Y)	2022	2022				
	Silverado 1500 New (RPO J22, VIN Digit 5 = A / D)						
GMC	Sierra	2019	2021				
	Sierra 1500 Limited (RPO J21, VIN Digit 5 = 8 / 9)	2022	2022				
	Sierra 1500 New (RPO J22, VIN Digit 5 = H / U)						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	3
Modified	Released August 16, 2022 Revised September 14, 2022 - Added Note under the Correction. Revised November 21, 2022 - Ended the need for gathering further information from the field.