Subject: Engineering Information - Vehicle Will Not Move When in Drive, Neutral and/or Reverse, DTCs P0746, P0747 Set

Brand:	Model:	Model Year:		VIN Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave	2018	2021	_	_	_	Equipped with RPO (M3W)
	Encore	2020					Equipped with RPO (M3F)
Cadillac	XT4	2019					Equipped with RPO (M3H)
	XT5	2020					Equipped with RPOs (M3G, M3W)
	XT6						
Chevrolet	Blazer	2019					Equipped with RPOs (M3V, M3T, M3D)
	Equinox	2018	2020				Equipped with RPO (M3D)
	Traverse		2021				Equipped with RPO (M3V)
GMC	Acadia	2020					Equipped with RPOs (M3H, M3G M3W)
	Terrain	2018					Equipped with RPOs (M3H, M3U)

This PI has been revised to end the need for gathering information from the field. Please discard PIE0720.

If you encounter a vehicle with the above condition, follow diagnostics for the DTC or transmission symptoms in SI.

Version	2
Modified	Released October 05, 2022 Revised November 22, 2022 — Ended the need for gathering further information from the field.