

Reference	SSM75895
Models	New Range Rover / L460
Title	22/23MY 4.4 NC10 P8H – Check Engine (Yellow) Illuminates, DTCs P013E-00 & P014A-00 Logged in the PCM
Category	Engine
Last modified	17-Nov-2022 00:00:00
Symptom	404000 Fuel System Concerns

Content**Issue:**

JAGUAR LAND ROVER is investigating customer reports of the check engine (yellow) warning lamp illuminating, with DTCs P013E-00 and P014A-00 logged in the Powertrain Control Module (PCM).

Cause:

Unknown at this time.

Action:

1. Confirm DTCs P013E-00 and P014A-00 are logged
2. Identify potential other DTCs and factors that may have triggered them (i.e., electrical connection, wiring harnesses, vehicle conditions)
3. Attach all the information identified plus the session file(s), photograph(s) and video(s) to either:
 - An ePQR, if you've rectified the customer symptom(s), quoting this SSM, along with the repair. Please hold onto the parts replaced, as per the warranty policy (30 days)
 - Or a Technical Assistance (TA) using this SSM number as a reference within the customer concern field and quoting PTS_160, which will be escalated directly to engineering

Thank you for your assistance with this investigation.

anBhdHRicm7MjAyMj0xMj0wNDczNT00NS4wNDIaOzEzNjYyNTIuMT10w==