# WNQ0 Workshop campaign - Check rear apron and re-paint it if necessary

## WNQ0 Workshop campaign - Check rear apron and repaint it if necessary

ID Number	WNQ0
Models	Taycan 4S (Y1A) / Taycan Turbo (Y1A)
Model Years	2020-2021
VIN List	Attached
Number of Affected VINs	3
Issue Description	On the affected vehicles, there is a possibility that top- coat color M6S -Mamba Green which does not meet the required specification has been applied to the rear apron.
	This can result in superficial damage, e.g. paint abra- sion, and may be regarded by the customer as a visu- al defect.
	In order to provide a better customer experience, the attached parts of the rear apron must be checked and repainted if there is any paint peeling.
What Dealers Should do	Please arrange for this measure to be carried out as soon as possible on affected vehicles. As of the time of this posting, the repair is immediately available.

#### TI Number

No. 206-22

#### **Required parts**

Part number	Designation	Quantity/vehicle	Parts return*
WNQ0000001*	Expendable items (mas- king materials, sanding materials and cleaning agents, paint in vehicle color)	1 unit	-

WNQ0000002**	Expendable items (mas- king materials, sanding materials and cleaning agents, paint in vehicle color)	1 unit
--------------	---	--------

\*For warranty processing, enter the Part No. WNQ00000001 with the designation "consumables" as an additional part costing \$37.50 in the warranty claim.

\*\*For warranty processing, enter the Part No. WNQ00000002 with the designation "consumables" as an additional part costing \$62.50 in the warranty claim.

#### Warranty processing

Validity:

This workshop campaign will be carried out up to September 22nd, 2027 and will be closed on that date. Please note that warranty claims can only be processed up to this date.

Scope 1: Checking rear aprons (attachment)

Damage Code	WNQ0 66 000
Repair Code	1
Labor time	15 TU

Scope 2: Checking rear aprons (attachment part) and repaint one rear apron - the painting of the rear apron was carried out in full by the Porsche Centre

Damage Code	WNQ0 66 000
Repair Code	1
Labor time	324 TU

Scope 3: Checking rear aprons (attachment part) and repaint both rear aprons - the painting of the rear aprons was carried out in full by the Porsche Centre

Damage Code	WNQ0 66 000
Repair Code	1
Labor time	354 TU

Scope 4: Checking rear aprons (attachment part) and repaint one rear apron - the painting of the rear apron was carried out by an external service provider

Damage Code	WNQ0 66 000
Repair Code	1
Labor time	154 TU
Sublet labor time	max. 170 TUs*

Scope 5: Checking rear aprons (attachment part) and repaint both rear aprons - the painting of the rear apron was carried out by an external service provider

Damage Code	WNQ0 66 000
Repair Code	1
Labor time	154 TU
Sublet labor time	max. 200 TUs*

\* The maximum amount that will be paid as outsourced labor time is the amount corresponding to the specified labor time based on the individual charging rate under warranty of the respective Porsche Dealer. Please include a copy of the invoice for external services with the warranty claim.

Please enter the campaign carried out in the warranty and maintenance booklet for the vehicle.

### **Customer mobility**

If requested, mobility for the affected customer can be guaranteed by offering a suitable replacement vehicle. Please invoice this additional service again via WWS with the campaign scope.