



RCA-78-22-013-1: Replace Body Control Module

Rivian is initiating a customer satisfaction campaign for some model year 2022 R1T vehicles which may have been built with a body control module (BCM) that was incorrectly assembled by the supplier. An incorrectly assembled BCM may cease functioning, which would cause an affected vehicle to enter a reduced performance safe state mode and a "Limited Performance Mode" indicator light will illuminate on the driver display. Although this condition has only been observed in one customer vehicle, it is possible that an affected vehicle could lose all exterior lighting and all electronic door locking functionality simultaneously with entering the reduced performance safe state mode. If a locked condition occurs, the vehicle can be exited by pulling the interior door handle twice. Rivian will replace the body control module in the affected vehicles. Rivian is launching this campaign for customer satisfaction and to ensure the quality of Rivian vehicles.

Document Type	Customer Satisfaction Campaign Bulletin
Date	November 3, 2022
Affected Region(s)	USA
Affected Model(s)	R1T
Model Year(s)	2022
Approximate Build Dates	August 2021 - December 2021
 Refer to the FSA Dashboard to determine if this document applies to a specific vehicle.	
Vehicle System	78 - Low Voltage Electrical
Minimum Service Location	Mobile

Required Parts

Part Number	Quantity	Engineering Name	Service Name/Notes
PT00012713-K	1	MODULE- BCM	Module, Body Control

 **Attention:** The parts listed in this table are only for unique steps that are called out in this bulletin. Some sections of this bulletin might refer to Service Manual procedures which require additional parts. Always review the bulletin and all potentially related Service Manual procedures before ordering parts and beginning work.

Procedure

Replace: Module, Body Control (refer to service manual procedure 782210010).

Labor Codes

Labor Code	Description
RCA782201300	RCA-78-22-013-1 not applicable
RCA782201301	Replace body control module
Contact ServiceDocumentFeedback@rivian.com regarding labor codes and document content.	