



Technical Service Bulletin

Technical Service Bulletin: TSB220219

Released Date: 28-Oct-2022

New Aftertreatment Intake NOx Sensor

New Aftertreatment Intake NOx Sensor

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- L9 CM2450 L126B

Description of Change

An aftertreatment intake NOx sensor part number is being released for service.

Reason for Change

This is a product improvement change that will help reduce aftertreatment intake NOx sensor malfunctions.

Service Instructions

- If existing aftertreatment intake NOx sensor has malfunctioned, replace with new aftertreatment intake NOx sensor as shown in Table 1.
- See L9 CM2450 L126B Service Manual, Bulletin. Refer to Procedure 019-463 in Section 19. (</qs3/pubsys2/xml/en/procedures/583/583-019-463.html>)

Service Parts

Service parts are offered. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Aftertreatment Intake NOx Sensor	4326867	No	No	5698480

Document History

Date	Details
2022-10-27	Module Created

Last Modified: 28-Oct-2022
