



Bulletin No.: PIT5883F
Published date: 11/29/2022

Preliminary Information

PIT5883F Information On Vehicles Built With Heated And Vented Seats Disabled / Heated Steering Wheel Disabled / Front Rear Park Assist Disabled / Wheel Well Liners / Column Lock / Rocker Protectors / Express Up Rear Windows / Adaptive Cruise Control / 120 Volt Power Outlet

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Enclave	2022 - 2023	All	All	All	All
Buick	Encore GX	2022 - 2023	All	All	All	All
Cadillac	CT4	2022 - 2023	All	All	All	All
Cadillac	CT5	2022 - 2023	All	All	All	All
Cadillac	Escalade Models	2022 - 2023	All	All	All	All
Cadillac	XT4	2022 - 2023	All	All	All	All
Cadillac	XT5	2022 - 2023	All	All	All	All
Cadillac	XT6	2022 - 2023	All	All	All	All
Chevrolet	Blazer	2022 - 2023	All	All	All	All
Chevrolet	Camaro	2022 - 2023	All	All	All	All
Chevrolet	Colorado	2022	All	All	All	All
Chevrolet	Corvette	2022 - 2023	All	All	All	All
Chevrolet	Equinox	2022 - 2023	All	All	All	All
Chevrolet	Malibu	202. - 20232	All	All	All	All
Chevrolet	Silverado LTD (RPO J21, VIN Digit 5 = Y or W)	2022	All	All	All	All
Chevrolet	Silverado 1500 New (RPO J22, VIN Digit 5 = D or A)	2022	All	All	All	All
Chevrolet	Silverado 1500	2023	All	All	All	All
Chevrolet	Silverado 2500/3500HD	2022 - 2023	All	All	All	All
Chevrolet	Suburban	2022 - 2023	All	All	All	All
Chevrolet	Tahoe	2022 - 2023	All	All	All	All
Chevrolet	Trailblazer	2022 - 2023	All	All	All	All
Chevrolet	Traverse	2022 - 2023	All	All	All	All
GMC	Acadia	2022 - 2023	All	All	All	All
GMC	Canyon	2022	All	All	All	All
GMC	Sierra Limited (RPO J21, VIN Digit 5 = 8 or 9)	2022	All	All	All	All
GMC	Sierra 1500 New (RPO J22, VIN Digit 5 = U or H)	2022	All	All	All	All

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
GMC	Sierra 1500	2023	All	All	All	All
GMC	Sierra 2500/3500HD	2022 - 2023	All	All	All	All
GMC	Terrain	2022 - 2023	All	All	All	All
GMC	Yukon Models	2022 - 2023	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	R6X, R7N, RFZ, 04O, 00G, 00N, 00R, 00V, 00Y, 08R, 07Z, and/or 00Z
Condition	<p>This is an informational PI to bring awareness to certain vehicle options being disabled. Please be aware that some vehicles, identified by an RPO code, are built with the following option(s) disabled:</p> <p>Front and/or Rear Park Assist disabled - RPO's 00Z or 00Y Heated Steering Wheel disabled - RPO 00G Heated/Vented Seats disabled - RPO 00V or 00R Not equipped with front seat cushion ventilation RPO 04O Not equipped with Electronic Steering Column Lock RPO R7N Not Equipped with Rocker Protector RPO R6X Not Equipped with Rear Wheelhouse Liner RPO RFZ Not Equipped with 2ND Row Express Up Window Control RPO 00N Not Equipped with Adaptive Cruise Control and Enhanced Auto Emergency Braking RPO 07Z Not Equipped with 120V AC Power Outlets RPO 08R</p>
Cause	Parts shortage

Correction:

If you have a vehicle with any of these RPO's and a complaint that the option does not work do not perform any repairs at this time. Please reference the following GM Global Connect messages for more information:

Front and Rear Park Assist Disabled - Reference Number: GCUS-17-429 (Canada GCCA-9-4306)

Heated Steering Wheel Disabled - Reference Number: GCUS-17-425 (Canada GCCA-9-4310)

Heated/Ventilated Seats Disabled - Reference Number: GCUS-17-424 (Canada GCCA-9-4307)

Not equipped with front seat cushion ventilation RPO 04O - Reference Number: GCUS-14-1576

Not equipped with Electronic Steering Column Lock RPO R7N - Reference Number: GCUS-14-1576

Not Equipped with Rocker Protector RPO R6X - Reference Number: GCUS-14-1587

Not Equipped with Rear Wheelhouse Liner RPO RFZ - Reference Number: GCUS-14-1573

Not Equipped with 2ND Row Express Up Window Control RPO 00N

Not Equipped with Adaptive Cruise Control and Enhanced Auto Emergency Braking RPO 07Z - Reference Ordering Workbooks / Dealer Ordering Guides

Not Equipped with 120V AC Power Outlets RPO 08R - Reference Number: GCUS-14-1644

NOTE: On vehicles with Heated Steering Wheel Disabled, DTC U152B may be set, but it does not turn on any warning messages or lights.

Additional SI Keywords

110, seat, volt, voltage,

Version History

Version	7
Modified	<p>01/10/2022 - Created on.</p> <p>01/18/2022- Updates to Condition and Model sections</p> <p>01/26/2022 - Update to correction section to add Canada Global message numbers</p> <p>08/11/2022 - Update to the model list</p> <p>08/18/2022 - Updates to the Model list, Title, Additional Options, Condition and Correction sections</p> <p>09/13/2022 - Updates to the Title, Additional Options, Condition and Correction sections</p> <p>11/01/2022 - Update to the Models, Title, Additional Options, Condition and Correction sections</p>



© 2022 General Motors. All Rights Reserved.