

GPOP - Issue Review System

Part Number:

68423990A\$,6TY831D7A\$,6TY871D7A\$,6TY881D7A\$,7JP501X7A\$,7JP511X7A\$,7KU501X7A\$,7KU511X7A\$,
,6TY851V7A\$,7KU481V7A\$,6TY841A6A\$,6TY841X7A\$,6TY842X7A\$,7JP521A6A\$,7JP521X7A\$,7JP522X7A\$,
,6TY861A6A\$,6TY861X7A\$,6TY862X7A\$,7KU761A6A\$,6VC911A6A\$,6VC912X7A\$,6TY891A6A\$,6TY891X7A\$,
,6TY892X7A\$,7JP531A6A\$,7JP531X7A\$,7JP532X7A\$,6TY901A6A\$,6TY901X7A\$

Part Description:

Steering Column Assembly, Steering wheel Assembly

**Issue
Description:**

Before replacing the steering gear assembly, steering column or steering wheel, for the following Fault codes:

C0051-54 (STEERING WHEEL POSITION SENSOR - MISSING CALIBRATION) or C0051-64 (STEERING ANGLE SENSOR (EPS) - SIGNAL PLAUSIBILITY FAILURE)
please see SOL # s2219000004 for diagnostics.