


Case Number: S2223000075

Release Date: October 2022

Symptom/Vehicle Issue: Front Fascia Cover Gaps And Or Poor Fitment.

**Discussion**: Simply removing and reinstalling the fascia may correct the appearance issue based on feedback from technicians. Refer to Service Library 13 - Frame and Bumpers / Bumpers / FASCIA, Front / Removal and Installation.



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.

## Stellantis US LLC