



NUMBER: 08-193-22

GROUP: 08 - Electrical

DATE: October 19, 2022

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 22-195, date of issue October 19, 2022. All applicable Sold and Un-Sold RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty. This RSU will expire 18 months after the date of issue.

SUBJECT:

Vehicle System Interface Module (VSIM) Jumper Harnesses Missing

OVERVIEW:

This bulletin involves adding three missing VSIM wiring jumper harnesses into rear cargo area.

MODELS:

2022 (WD) Dodge Durango

NOTE: This bulletin applies to vehicles within the following markets/countries: North America.

NOTE: This bulletin applies to vehicles built on or after June 17, 2022 (MDH 0617XX) and on or before August 08, 2022 (MDH 0808XX) equipped with Police Group (Sales Code AYF).

SYMPTOM/CONDITION:

Vehicles missing all three jumper harnesses from the trunk kit to use when installing police equipment (lights, sirens, etc.) to the VSIM.

NOTE: This service bulletin only pertains to Model WDEE75 Dodge Durango Pursuit Vehicle - All Wheel Drive (AWD).

PARTS REQUIRED:

Qty.	Part No.	Description
1	68251804AA	Jumper - Instrument Panel, Wiring
1	68251805AA	Jumper - Auxiliary PDC, Wiring
1	68518169AA	Jumper, Wiring

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RSU VIN list, perform the Repair Procedure. **This RSU only applies to vehicles on the RSU VIN list.**

REPAIR PROCEDURE:

1. Place all three wiring harness jumpers (Fig. 1) into the rear cargo area.



Fig. 1
Three VSIM Wiring Jumper Harnesses

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
08-19-19-90	VSIM Wire Jumper Harness, Add Three Missing Wire Jumpers Into Rear Cargo Area with Existing Kit (0 - Introduction)	6 - Electrical and Body Systems	0.0 Hrs.

RELATED OPERATION:

Labor Operation No:	Description	Skill Category	Amount
95-23-30-55	Handling Fee for Inserting Three VSIM Wire Harnesses Into Cargo Area	6 - Electrical and Body Systems	\$5.00

FAILURE CODE:

ZZ	Service Action
----	----------------