

**Subject: Engineering Information - Radio Staying On After Retained Accessory Power (RAP), Low and/or Dead Battery**

*This PI has been revised to end the need for gathering information from the field. Please discard PIE0724.*

Brand:	Model:	Model Year:		VIN Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Buick	Envision	2022	2022	—	—	—	—
Chevrolet	Silverado 1500 New (RPO J22, VIN Digit 5 = A / D)	2022	2022	—	—	—	—
	Silverado 1500 LTD (RPO J21, VIN Digit 5 = W / Y)						
GMC	Sierra 1500 New (RPO J22, VIN Digit 5 = H / U)	2022	2022	—	—	—	—
	Sierra 1500 Limited (RPO J21, VIN Digit 5 = 8 / 9)						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

<b>Version</b>	2
<b>Modified</b>	Released October 28, 2022 Revised December 01, 2022 - Ended the need for gathering further information from the field.