

### 01 DTC P060C00 is stored in the ECM - Repair Authorization

01 22 29 2068614/1 December 5, 2022.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q8, SQ8, and RS Q8	2021 – 2022	All	Not Applicable

# Condition

#### **Customer states:**

MIL on.

#### Workshop findings:

The following DTC may be stored in the engine control module ECM, J623 (address word 001): **DTC P060C00** (Internal Control Module Main Processor Performance) with **symptom code 30924**.

## **Technical Background**

This is a rare occurrence and is caused by the sensitivity of diagnostics software in the ECM, J623 (address word 0001).

## **Production Solution**

No changes to production have been made, as no issue has been identified.

## **Service**

This TSB replaces Pending Service Solution (PSS) TSB 2062142. Please refer to TSB 2068506 for MY20 vehicles.

Audi of America is requesting your cooperation in supplying us with technical information regarding this condition.

Verify the condition.

If the vehicle is within the New Vehicle Limited Warranty, contact a TAC consultant before proceeding. Please attach the DTC and diagnostic log to the TAC ticket/TAC Web Ticket.

## Warranty

This TSB is informational only and not applicable to any Audi warranty.

© 2022 Audi of America, Inc.

Page 1 of 2

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



## **Required Parts and Tools**

Tool Number	Tool Description	
VAS 6160/VAS 6150	VAS tester with the current version of ODIS (Windows 10)	

# **Additional Information**

All parts and service references provided in this TSB (**2068614**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

© 2022 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.