


Technical Service Bulletin



PSS 90 Audi Virtual Cockpit: Turn signal is sound unusually loud

90 22 87 2068300/2 December 12, 2022. Supersedes Technical Service Bulletin Group 90 number 22-79 dated October 19, 2022 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6 allroad, A6, RS 6 Avant, A7, A7 e quattro, S7, RS 7, A8, A8 e quattro, S8, Q7, SQ7, Q7, SQ8, and RS Q8	2021	All	Virtual Cockpit

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header (Updated PR Number Filter)
1	10/19/2022	Initial publication

Customer states:

The clicking sound is audible when the turn signal is active and is sporadically unusually loud.

Workshop findings:

No relevant DTCs are stored.

Technical Background


A software-related issue may cause the complaint described above.

Production Solution

Not applicable.

Service

1. Explain to the customer that a solution is expected to be available by the end of the 2nd quarter of 2023 (subject to change) and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.
2. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links* >> *Service*), or through the Technical Assistance page in Elsa.



Workaround

After cycling the ignition off and back on, the complaint should be temporarily resolved.

Warranty

This TSB is informational only and not applicable to any Audi warranty.

Additional Information

All part and service references provided in this TSB (**2068300**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.