

MAS003291 MSC 22-49

Campaign 529

FROM: Maserati TSO

TO: Maserati Network



Maserati

PERSONAL SERVICE LAB

MASTERS OF CARE

Service Campaign 529

MC20 - Installation of new auxiliary pulley for water pump

To be carried out at the same time as the second scheduled service



DATE: November 17, 2022

Certain Maserati MY22 MC20 V6 listed in MODISCS+ are involved in a Service Campaign relating to replacement of the auxiliary belt water pump pulley.

This operation is necessary to introduce a new auxiliary pulley, which improves the performance of the belt loop. The resulting benefit relates only to improved performance in terms of the service life of affected components such as the water pump.

This work should be organized during the second service, when service belt replacement is already prescribed in the scheduled service plan. Only the auxiliary pulley will be reimbursed under the campaign.

We would like to remind you that, pursuant to Maserati policies, all Service Campaigns must be carried out when the vehicle first arrives at the workshop, following the technical instructions given in this information notice, regardless of the Mandatory setting in Modis. In this specific case, the work must be carried out at the same time as the second service.



Please read and review this bulletin first before starting the procedure.
Contact your Regional AfterSales Manager (RAM) or the Technical Support Helpdesk if you have any questions. (Maseratitechsupport@maserati.com)

Thank You for your continued support and cooperation.

Maserati Americas
Aftersales Dept.

Operational Procedure

1. Verify that:
 - The vehicle is involved in the action and that the campaign has not already been carried out
 - The vehicle is to undergo the second service according to the scheduled service plan.



2. During scheduled servicing, when replacing the compressor drive belt, install the new belt tensioner pulley (part. #1 in the figure) following the procedure described:

01.11.005 - PULLEY TENSIONER - Removal-Refitting or Replacement

3. Proceed with the operations set out in the service plan.
4. The operation can be considered complete.

Spare Parts

The following PNs must be ordered from the Maserati Spares Department for this campaign. Please refer to the Vin List to verify the quantities to be ordered for each service point based on the cars involved, so that the service can be carried out at the same time as the second service without inconveniencing the customer.

Description	PN
Auxiliary pulley	670054341
Bushing	670050111

Warranty Claim

Complete the warranty claim as follows:

Description	Code
Campaign Number	529
Warranty Code	23
Fault Code	063
Component Code	1.11.005
Operation Code	1.11.005.A (0.05h) *

(* Please note that since the operation is carried out during the vehicle's normal scheduled (routine) service plan, replacement of the belts and the related labour remain at the customer's expense, as also communicated in the service plan published in the vehicle on board documentation.

Maserati is responsible for the auxiliary pulley, which will be installed during the routine service.