

Case Number: S2208000096

Release Date: April 2022

Symptom/Vehicle Issue: Park Assist Is Not Equipped On Vehicles With Sales Code XA5 Or XP1

Discussion: Vehicles equipped with sales code XA5 OR XP1 - Parksense Park Assist Unavailable will come with a "dummy" Park Assist Module (PAM). The PAM will not be active on the bus. The PAM has no functionality and is only there to secure the existing wiring.

At a later date, a new harness will be implemented which will eliminate the PAM wiring and connectors.

Information only. No diagnostics or repairs are required.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found