Next Unread Message

View Message

			_							
Sent on	12	13	2022	Expires on	12	16	2022			
F			<u> </u>	·			ļ			
From	Technical Information & Support Group									
Subject	Request for Visit: 2020-2021 Accord & Civic 2.0L Oil Leak from Head Cover Gasket									
	j ·									

PRIORITY/ACTION REQUIRED

To: All Honda Service Managers/Advisors From: Technical Information & Support Group

RE: Request for Visit: 2020-2021 Accord & Civic 2.0L Oil Leak from Head Cover Gasket

(ACTION REQUIRED)

This message is solely directed to Honda dealership personnel; please handle it accordingly. Print this iN message and provide a copy to the Shop Foreman and all Service Advisors.

Background

American Honda Motor Co., Inc. (AHM) is investigating certain 2020-2021 Accord 2.0Ls & Civic 2.0Ls with a customer complaint of an oil leak or a dealer technician noticing an oil leak from the head cover gasket during a routine maintenance. To fully understand the cause of this condition, AHM would like to inspect the vehicle prior to you attempting a repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirement:

- 1. Must confirm oil leak is from the head cover gasket.
- 2. No repair has been attempted for this issue including cleaning the area of suspected oil leak.

Action Required

If a vehicle matching the description above comes into your dealership, please e-mail Technical Information & Support at <u>tis@ahm.honda.com</u>. TIS will contact you to record certain vehicle information and provide you with further instructions.

Please be sure to include the following information in your e-mail.

E-mail Title:

- 1. Model Year (e.g. 2020)
- 2. Model Name (e.g. Accord)
- 3. Issue (e.g. Brake Judder)
- 4. VIN

E-Mail Body:

- 1. Dealer Number
- 2. Your Name
- 3. Best Phone Number to reach you
- 4. Current Mileage

Thank you.