

Subject: Engineering Information - Horn Having Weak Sound and/or Horn Inoperable

This PI has been revised to end the need for gathering information from the field. Please discard PIE0713.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500 New (RPO J22, VIN Digit 5 = A / D)	2022	2022	—	—	—	—
GMC	Sierra 1500 New (RPO J22, VIN Digit 5 = H / U)						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released August 11, 2022 Revised December 08, 2022 - Ended the need for gathering further information from the field.