

REFERENCE:	Nova Bus Manuals
SECTION:	10: Transmission and Control
RS N°:	MQR 7621-2517
EFFECTIVE IN PROD.:	N/A

APPLICATION DEADLINE: 2024JN07
CLAIM REFERENCE NUMBER: WB-5318

SUBJECT:	Transmission dipstick replacement.
JUSTIFICATION:	Dipstick does not reflect the correct Oil level in the transmission.

LEVEL	DESCRIPTION	DIRECT CHARGES		TIME
		LABOUR	MATERIAL	
1	Replacement of Transmission dipstick.	Client	Novabus	–
2	–	–	–	–

MATERIAL REQUIRED PER VEHICLE

QTY	PART N°	REV.	DESCRIPTION
LEVEL 1			
1	N107355	–	DIPSTICK TRANS OIL VOITH
LEVEL 2			
–	–	–	–

Materials will be available within 118 days once your order has been placed.

To order, please contact novabus.parts@volvo.com

Or by phone for CANADA 1-800-771-6682, for USA 1-877-999-8808

Specify document number, quantity of parts required and shipping address.

DISPOSAL OF PARTS

REMOVED PARTS ARE:	DISCARDED*	RETAINED	* Dispose of the unused parts and the defective parts in accordance with local environmental standards in effect.
	Yes	–	

REVISION HISTORY

REV.	DATE	CHANGE DESCRIPTION	WRITTEN BY
NR	2022DE15	Initial release	Devanand

APPROVED BY:

PAGE 1 OF 3

CLIENT	ORDER	ROAD NUMBER		VIN (2NVY/4RKY...)		QTY
		FROM	TO	FROM	TO	
Trimet Portland Oregon	LD14	4501	4501	S92J3M9777922	S92J3M9777922	1
Trimet Portland Oregon	LD15	4502	4531	S92J6M9778188	S92J7N9778296	30

**WARNING****FOLLOW YOUR INTERNAL SAFETY PROCEDURES.**

- 1.1. Park the vehicle on an even surface with the transmission on neutral.
- 1.2. Apply the parking brake and set the master control switch to the **stop** position.
- 1.3. Set the battery disconnect switch in the battery compartment to the **off** position
- 1.4. Open rear engine access door.
- 1.5. Remove oil level Dipstick N57701 and discard. See Figure 1.
- 1.6. Install new oil level Dipstick N107355.
- 1.7. Close rear engine access door.❖




Figure 1 - Transmission Dipstick