

2022 Ascent

. WATER PRESSURE IN KITCHEN SINK IS LOW. During the testing found no water flow to the kitchen faucet. Will need to remove 3 drawers and panel inside the compartment to access to the water lines. Found a bent line. Will also need to remove one of the 2 weights and install on the top of the bent hose and test for proper function time require 1.0 0.50 approved. R/I the 3 drawers is less than 2 minutes to do. The panel at the back to R/I is less than 2 minutes because its only held by some screws.

2023 Ascent

P) DURING PDI FOUND FRESH INLET HAS WATER BACK FLOWING WHEN FILLING FRESH TANK
C) VENT HOSE FROM TANK TO OUTSIDE CONNECTION WAS KINKED.
R) I TOOK PART THE COACH TO FIND THE BACK OF THE FRESH TANK INLET, TO SEE WHERE THE INLET LED TO. FOUND THE HOSE FROM TANK TO THE OUTSIDE CONNECTION. HOSE AT TANK WAS KINK. VENT HOSE WAS TO LONG HAD TO TAKE CONNECTION OFF FROM OUTSIDE CONNECTION TO CUT IT SHORTER. THEN REATTACHED HOSE. REMOVED KINK FROM HOSE. TEST AND NO BACK FLOW
TIME 1.0 HRS 1.0 approved.