

2022 Ascent

2.Complaint: Heat shield had come off fresh tank-- Documented with PW as PW sent customer the shield
Cause shield not adhered properly to tank. Resolution- Lift vehicle and install heat shield on innermost side of tank. Time .3 hrs
0.50 approved.