

Subject

Visor swing-arm hinge cover missing

Market

USA

Service Category

Vehicle Interior

Section

Interior Panels/Trim

Applicability

MY23 Sienna HV


APPLICABLE VEHICLES

2023

Sienna HV

CONDITION

Some customers as well as dealerships conducting PDI may realize the covers for the visor bolt plate on 2023 Sienna HV are no longer present. The covers are no longer being included in the assembly of the vehicle.



RECOMMENDATIONS

Dealerships may still order the visor bracket cover (74317-08030 for RH and 74318-08030 for LH) as located in EPC for 2021 and 2022 Sienna HV models but will not be covered as a warrantable repair.



LINK REFERENCES

1. [INTERIOR PANELS / TRIM: ROOF HEADLINING: INSTALLATION; 2021 - 2023 MY Sienna HV \[11/2020 - ???????\]](#)