

N748 UPS6822-1 – POWERED LOADSPACE COVER



CAMPAIGN - UPDATE PRIOR TO SALE N748 – POWERED LOAD SPACE COVER

AFFECTED MODELS	22-23MY New Range Rover
VOLUME AFFECTED	USA 837
REPAIR	On certain 22-23 MY Range Rover vehicles, the powered load space cover requires an inspection for its operation and if needed, install felt pads.
REPAIR TIME	0.1 hrs + DIDO
CAMPAIGN LAUNCH	November 17 th , 2022
Notes	Repairs are also being performed in ports of entry. There are 18 affected vehicles in retailer inventory. Please check the Warranty Portal or BBSS inventory reports for any affected VIN at your store and ensure these vehicles are updated prior to sale.