



NUMBER: 23-011-22

GROUP: 23 - Body

DATE: March 11, 2022

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 22-049, date of issue March 11, 2022. All applicable Sold and Un-Sold RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty. This RSU will expire 18 months after the date of issue.

SUBJECT:

Missing front license plate bracket

OVERVIEW:

This bulletin involves installing a missing front license plate bracket.

MODELS:

2021 - 2022 (JT) Jeep Gladiator

NOTE: This bulletin applies to vehicles within the following market/country: North America.

NOTE: This bulletin applies to vehicles built on or after September 26, 2020 (MDH 0926XX) and on or before January 26, 2022 (MDH 0126XX) equipped with Customer Preferred Package 2TT (Sales Code 2TT) and Customer Preferred Package 2TW (Sales Code 2TW).

SYMPTOM/CONDITION:

Customer may comment on the following:

- Front licence plate bracket missing.

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. **This RSU only applies to vehicles on the RSU VIN list.**

PARTS REQUIRED:

Qty.	Part No.	Description
1	68293738AA	Plate Kit (Includes Fasteners)

REPAIR PROCEDURE:

1. Install the front license plate bracket only if a front license plate is required by the state/province, use LOP (13-05-01-91).

NOTE: If the state/province does not required a front license plate, place the new license plate bracket kit in the vehicle. (Do not install without customers consent), use inspect LOP (13-05-01-90) to close the active RSU.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
13-05-01-90	Bracket, Front License Plate - Inspect or place in vehicle (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
13-05-01-91	Bracket, Front License Plate - Inspect and Install (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------