

Technical Journal

TITLE:

“Sticky” rear brake pads

REF NO: TJ 36169.3.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA, LLC		ISSUE DATE: 2022-11-22	STATUS DATE: 2022-11-28
FUNC GROUP: 5125	FUNC DESC: Brake pad; brake pad kit	Page 1 of 2	

“Right first time in Time”

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

* Updated Vehicle Type and Service information.

If the customer experience loud sound and/or heavy vibrations from the rear , please follow advice under Service.

CSC Customer Symptom Codes

Code	Description
1P	Brakes/Unusual noise/Rear
V3	Brake pedal/Pulsations
V4	Brakes/Vibration/shudder/While braking

Technical Journal 36169.3.0

DTC Diagnostic Trouble Codes

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
536	EC	E400V5					2022-2023			202146-202246
536	ED	E400V6					2021-2023			202037-202246
536	EF	E400V2					2022-2023			202146-202246
539	EC	E400V5					2022-2023			202139-202246
539	ED	E400V6					2022-2023			202139-202246
539	EF	E400V2					2022-2023			202139-202246

SERVICE:

If the symptom is confirmed, proceed with replacement of the rear brake pads according to the VIDA.

Note: In some cases, Brake discs may need to be replaced. Proceed with following steps before replacement: visual check of the Brake disc and/or cleaning with sandpaper/brushing.

If the Brake disc is judged as damaged, proceed with replacement according to the VIDA.

In case of replacement of the Brake discs, Vehicle Report should be created with pictures of the damaged discs.

Warranty claim info:

To get warranty claim accepted for a job described in this TJ, please use following data:

VST OP Number: 51204-0.