





USE THREAD REPAIR TOOL FOR U90 OR UA3 EMISSIONS RECALL REPAIR

Some of the maniverter bolts or studs may break, or the cylinder head threads may strip when performing the U90 or UA3 Emissions recall repair.




Maniverter to Engine



Inspect for Thread Loss

If this occurs, **DO NOT ATTEMPT TO EXTRACT THE BOLTS OR STUDS**, use the special tool **2073500090 - Kit, Cylinder Head Thread Repair - 2.4L MAIR** to perform the helicoil thread repair operation by following the service instructions published in **DealerCONNECT / Service Library / Engine, 2.4L Multiair / Standard Procedure / Exhaust Manifold Fastener Hole Repair**. Each U.S. dealership was previously given a 2073500090 tool kit.



2073500090 - Kit, Cylinder Head Thread Repair - 2.4L MAIR

Thank you,

Mopar

