WNS7 Workshop campaign - Reprogramming air-conditioning system control unit

WNS7 Workshop campaign - Re-programming airconditioning system control unit

ID Number WNS7

Models Macan (95B)
Model Years 2022 - 2023
VIN List Attached
Number of Affected VINs 25,306

Issue Description On the affected vehicles, due to a software error, it is

possible that low current limits are sporadically transmitted from the air-conditioning system control unit to the air conditioning fan, especially when using the

permanent driving lights.

If this is the case, the ventilation of the vehicle interior

is impaired by the air conditioning fan.

For this reason, the air-conditioning system control unit of the affected vehicles must be re-programmed

with an updated data set.

What Dealers Should do Please arrange for this measure to be carried out as

soon as possible on affected vehicles. As of the time of this posting, the repair is immediately available.

TI Number No. 233-22

Customer Letter To be posted at a later date.

Required software

PIWIS Tester 3 test software version 41.400.020 (or higher)

Warranty processing

Validity:

The current workshop campaign will be carried out by November 10th, 2027 and will be closed on that date. Please note that warranty claims can only be processed before this date.

Scope 1:

Damage Code WNS7 66 000

Repair Code 1

Labor time 33 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.